

Halden Maritime Insurance

Notice of Survey Findings

Reference HM-SUR-2026-0431

Findings of the Condition Survey

The survey was carried out afloat at the berth nominated by the owner, with the vessel in a light condition and all compartments accessible to the attending surveyor.

Hull plating was gauged at the positions marked on the attached plan, and every reading returned a thickness within the allowance stated in the class rules for the vessel's age.

The cargo hold bilge alarms were function tested and found to operate correctly, although the starboard sensor required cleaning before it would respond within the required time.

Recommendations arising from the survey are listed in the schedule at the end of this notice, together with the date by which each is to be completed to the satisfaction of the attending surveyor.