## **PROGRAM**

1000 MOV AH,[1100]

1004 ADD AX,[1102]

1008 JNC 100B

100B INC CX

100D MOV [1200],AX

100F MOV [1202],CX

1013 HLT

## **OUTPUT**

INPUT OUTPUT

[1100]=FC34 [1200]=52FE

[1102]=56CA [1202]=01