Construction Chemicals

Product Datasheet
Edition: 01 | Date: Nov 2026
Protective Coating

O-Zinc I

Zinc-Rich Epoxy Primer
Cathodic Protection for Steel



Product Description

O-Zinc I is a two-component, zinc-rich epoxy primer that provides cathodic (galvanic) protection to steel. It is non-toxic, dries quickly, is weldable, and can be used as a primer or as a self-finish. It also improves the protection of exposed reinforcement bars before concrete repair.

Uses

- Roads and bridges.
- Workshops and warehouses.
- Car parks and staircases.
- Steel structures and fabrications.
- Protection of exposed reinforcement bars.

Advantages

- Cathodic protection of steel.
- Fast drying and non-toxic.
- Weldable.
- Primer or self-finish.
- Improves rebar protection in repairs.

Application

1. **Surface Preparation**
   Blast-clean steel to Sa 2½; remove dust.
2. **Mixing**
   Mix Part A thoroughly, add Part B and mix until uniform; thin max. 5 %.
3. **Application**
   Apply by brush, roller or spray at 0.15 – 0.20 kg/m² per 50 µm.

Consumption

0.15 – 0.20 kg/m²
per 50 µm DFT
Keep zinc in suspension by stirring during use.

Packaging

5 kg, 20 kg and 25 kg sets (Part A + Part B), metal pails.

Storage & Shelf Life

12 months in original, unopened packaging. Store dry at +5 °C to +35 °C, away from direct sunlight.

Technical Data

Typical values at 25 °C

Property	Typical Value	Test Method
Mixing ratio	As recommended — pre-weighed sets	—
Colour	Grey	—
Solids content	57 ± 2 %	—
Density	1.6 kg/L	—
Pot life	3 hours	—
Recoat	5 – 12 hours	—
Full cure	7 days	—
Flash point	126 °C	—
Thinning	max. 5 %	—
Min. steel temperature	+5 °C	—

Consumption

DFT	Consumption
50 µm	0.15 – 0.20 kg/m²
75 µm	0.23 – 0.30 kg/m²

Consumption is theoretical and varies with substrate porosity, profile and application method.

Application Conditions

- Steel temperature: min. +5 °C, at least 3 °C above dew point.
- Relative humidity: max. 85 %.
- Steel blast-cleaned to Sa 2½.

Application Notes

- Stir continuously to keep zinc in suspension.
- Thin max. 5 % with the recommended thinner.
- Apply a stripe coat on edges and welds.
- Overcoat with the specified intermediate or top coat within the recoat window.

Health & Safety

- Solvent-based: flammable. Keep away from heat, sparks and open flames; no smoking.
- Wear chemical-resistant gloves, safety goggles and overalls; use a respirator with organic vapour cartridges in enclosed spaces.
- Uncured resin may cause skin sensitisation; avoid skin and eye contact.
- Ensure good ventilation during application and curing.

First Aid & Cleaning

- Eyes: rinse immediately with plenty of clean water for at least 15 minutes and seek medical advice.
- Skin: remove contaminated clothing and wash with soap and water; do not use solvents on skin.
- Inhalation: move to fresh air; seek medical advice if symptoms persist.
- Ingestion: do not induce vomiting; seek medical advice immediately.
- Clean tools with the recommended thinner before the material cures.