Construction Chemicals

Product Datasheet
Edition: 01 | Date: Nov 2026
Protective Coating

O-Prime ZP

Chromate-Free Zinc Phosphate
High-Build Epoxy Primer



Product Description

O-Prime ZP is a two-component, high-build, chromate-free zinc phosphate epoxy primer for steel structures and tanks. It is the base primer for epoxy and polyurethane systems.

Uses

- Steel structures and frames.
- Tanks and vessels (external).
- Primer under O MIX epoxy and PU coatings.

Advantages

- Anti-corrosive zinc phosphate.
- Chromate-free.
- High build: 75 – 150 µm per coat.
- Base for epoxy and PU systems.
- Recoat 6 – 12 hours.

Application

1. **Surface Preparation**
   Blast-clean steel to Sa 2½.
2. **Mixing**
   Mix Part A and Part B 1 : 1 by volume until uniform.
3. **Application**
   Apply by brush, roller or airless spray at 75 – 150 µm DFT.

Consumption

6 – 7 m²/L
at 100 µm DFT
Approx. 0.21 – 0.25 kg/m² at 100 µm.

Packaging

5 kg and 20 kg sets (Part A + Part B), metal pails.

Storage & Shelf Life

12 months in original, unopened packaging. Store dry at +5 °C to +35 °C, away from direct sunlight.

Technical Data

Typical values at 25 °C

Property	Typical Value	Test Method
Mixing ratio (A : B)	1 : 1 by volume — pre-weighed sets, mix as recommended	—
Finish / colours	Matt; red oxide, grey	—
Density	1.4 – 1.6 kg/L	—
Solids content	60 – 70 %	—
DFT per coat	75 – 150 µm	—
Touch dry	2 – 4 hours	—
Recoat	6 – 12 hours	—
Shelf life	12 months	—

Consumption

DFT	Coverage
75 µm	approx. 8 – 9 m²/L
100 µm	6 – 7 m²/L
150 µm	approx. 4 – 4.7 m²/L

Consumption is theoretical and varies with substrate porosity, profile and application method.

Application Conditions

- Steel temperature at least 3 °C above dew point.
- Relative humidity: max. 85 %.
- Steel blast-cleaned to Sa 2½.

Application Notes

- Blast-clean to Sa 2½ before priming.
- Apply stripe coats on edges and welds.
- Overcoat within the recoat window.
- Measure DFT after each coat.

Health & Safety

- Solvent-based: flammable. Keep away from heat, sparks and open flames; no smoking.
- Wear chemical-resistant gloves, safety goggles and overalls; use a respirator with organic vapour cartridges in enclosed spaces.
- Uncured resin may cause skin sensitisation; avoid skin and eye contact.
- Ensure good ventilation during application and curing.

First Aid & Cleaning

- Eyes: rinse immediately with plenty of clean water for at least 15 minutes and seek medical advice.
- Skin: remove contaminated clothing and wash with soap and water; do not use solvents on skin.
- Inhalation: move to fresh air; seek medical advice if symptoms persist.
- Ingestion: do not induce vomiting; seek medical advice immediately.
- Clean tools with the recommended thinner before the material cures.

The information in this datasheet is based on laboratory tests and practical experience and is given in good faith. Users should verify product suitability for their specific application. O MIX reserves the right to update this information without prior notice.