Rm = 0.1 ohms, Vbatt = 7.2 V, Rbat = 0. Vds = $3.6V \rightarrow Ids = (7.2-3.6V)/(0.1 ohm) = 36 amps$

