



Repair Estimate

Ignition Coil Replacement

Tripoint Diagnostics Ltd

Company No. 17038307

Registered office: 476 Sidcup Road, London, United Kingdom, SE9 4HA

VAT No.: Pending (HMRC application in progress) Website: tripointdiagnostics.co.uk

Email: contact@tripointdiagnostics.co.uk | Phone: [020 8058 6095](tel:02080586095)

WhatsApp: [Message us](#) | [Google Business](#)

ESTIMATE NUMBER

EST-2026-0003

STATUS

ESTIMATE

ESTIMATE DATE

12 April 2026

DUE DATE

Valid for 30 days

PAYMENT TERMS

Estimate

BILL TO

David

leytonpolishcraft@gmail.com

07436 260756

SERVICE ADDRESS

Customer location

RM1 4XR

Vehicle: 2017 Mercedes-Benz GLA 200 AMG Line Premium Plus (AD17BJX) **Odometer:** - **Job**
ID: EST-2026-0003 **PO:** -
Technician: Jamie Armoordon

DESCRIPTION	QTY	RATE	AMOUNT
Parts: Authentic Mercedes Ignition Coil Genuine Mercedes-Benz replacement ignition coil. Includes standard manufacturer parts warranty.	2	£75.83	£151.67
Labour: Mobile Callout & Installation Travel to vehicle location and up to 1 hour of on-site labour. Includes: Remove engine cover, replace 2x ignition coils, perform post-repair functional check & clear related fault codes.	1 hr	£120.00	£120.00

Subtotal	£271.67
Discount	None
VAT (20%)	£54.33
Total	£326.00
Amount paid	£0.00
Balance due	£326.00

Payment

This is an estimate. Do not pay. To proceed, please contact us to schedule the repair.

Notes: Estimate based on genuine Mercedes-Benz parts. Labour covers 1st hour including mobile callout to location, fitment, and post-repair XENTRY clearing/testing.

VAT Notice: All prices include VAT at 20%. VAT registration is currently being processed by HMRC. A full VAT invoice with our VAT Registration Number will be reissued once our VRN has been confirmed.