



Repair Estimate

Ignition Coil Replacement

Tripoint Diagnostics Ltd

Company No. 17038307

Registered office: 476 Sidcup Road, London, United Kingdom, SE9 4HA

VAT No.: 515 7327 92 Website: tripointdiagnostics.co.uk

Email: contact@tripointdiagnostics.co.uk | Phone: [020 8058 6095](tel:02080586095)

WhatsApp: [Message us](#) | [Google Business](#)

ESTIMATE NUMBER

EST-2026-0004

STATUS

ESTIMATE

ESTIMATE DATE

12 April 2026

DUE DATE

Valid for 30 days

PAYMENT TERMS

Estimate

BILL TO

David

leytonpolishcraft@gmail.com

07436 260756

SERVICE ADDRESS

Customer location

RM1 4XR

Vehicle: 2017 Mercedes-Benz GLA 200 AMG Line Premium Plus (AD17BJX) **Odometer:** - **Job**
ID: EST-2026-0004 **PO:** -
Technician: Jamie Armoordon

DESCRIPTION	QTY	RATE	AMOUNT
Parts: Authentic Mercedes Ignition Coil Genuine Mercedes-Benz replacement ignition coil. Includes standard manufacturer parts warranty.	4	£75.83	£303.33
Labour: Mobile Callout & Installation Travel to vehicle location and up to 1 hour of on-site labour. Includes: Remove engine cover, replace 4x ignition coils, perform post-repair functional check & clear related fault codes.	1 hr	£120.00	£120.00

Subtotal	£423.33
Discount	None
VAT (20%)	£84.67
Total	£508.00
Amount paid	£0.00
Balance due	£508.00

Payment

This is an estimate. Do not pay. To proceed, please contact us to schedule the repair.

Notes: Estimate based on genuine Mercedes-Benz parts. Labour covers 1st hour including mobile callout to location, fitment, and post-repair XENTRY clearing/testing.