



# Estimate

Auxiliary Belt & Tensioner Replacement

## Tripont Diagnostics Ltd

Company No. 17038307

Registered office: 476 Sidcup Road, London, United Kingdom, SE9 4HA

**VAT No.:** 515 7327 92 Website: [tripointdiagnostics.co.uk](http://tripointdiagnostics.co.uk)

Email: [contact@tripointdiagnostics.co.uk](mailto:contact@tripointdiagnostics.co.uk) | Phone: [020 8058 6095](tel:02080586095)

WhatsApp: [Message us](#) | [Google Business](#)

ESTIMATE NUMBER

**EST-2026-0014**

STATUS

**ESTIMATE**

ESTIMATE DATE

**19 May 2026**

DUE DATE

**Valid for 30 days**

PAYMENT TERMS

**Estimate**

BILL TO

Tom Millen (Archie's Castles & Soft Play)

SERVICE ADDRESS

Fermain, The Street  
Sittingbourne, ME9 8JN

Fermain  
The Street  
Sittingbourne, Kent  
ME9 8JN

**Vehicle:** Mercedes-Benz Sprinter (KR70 PWE) **Odometer:** - **Job ID:** EST-2026-0014 **PO:** -  
**Technician:** Jamie Armoordon

| DESCRIPTION                                                                                                                                                                                                                                                        | QTY                                                                                               | RATE               | AMOUNT        |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------|--------------------|---------------|
| PARTS (GENUINE MERCEDES-BENZ)                                                                                                                                                                                                                                      |                                                                                                   |                    |               |
| <b>Genuine Mercedes-Benz Belt Tensioner</b><br>Part No. A6542000070<br>OE auxiliary-belt tensioner assembly. Supplied at £106.45 inc VAT (£88.71 ex VAT).                                                                                                          | 1                                                                                                 | £88.71             | £88.71        |
| <b>Genuine Mercedes-Benz Poly-V-Belt</b><br>Part No. A0009939500<br>OE multi-rib (poly-V) auxiliary drive belt. Supplied at £33.99 inc VAT (£28.33 ex VAT).                                                                                                        | 1                                                                                                 | £28.33             | £28.33        |
| LABOUR                                                                                                                                                                                                                                                             |                                                                                                   |                    |               |
| <b>Mobile Callout</b><br>Standard mobile callout fee <b>waived</b> as a thank-you for repeat business.                                                                                                                                                             | 1                                                                                                 | <del>£120.00</del> | <b>WAIVED</b> |
| <b>Auxiliary Belt &amp; Tensioner Replacement</b><br>Remove and replace auxiliary (poly-V) drive belt and belt tensioner assembly, inspect pulleys, refit and verify operation. Charged at the standard hourly rate of £85.00 + VAT per XENTRY manufacturer times. | 0.9 hrs                                                                                           | £85.00             | £76.50        |
| XENTRY LABOUR BREAKDOWN (0.9 HRS TOTAL)                                                                                                                                                                                                                            |                                                                                                   |                    |               |
| 13-1202                                                                                                                                                                                                                                                            | Replace V-belt on vehicle with single-belt drive                                                  |                    | 0.7 H         |
| 13-3209                                                                                                                                                                                                                                                            | Remove/install tensioning device for V-belt, replace assembly parts if necessary (V-belt removed) |                    | 0.2 H         |

|             |                                         |
|-------------|-----------------------------------------|
| Subtotal    | £193.54                                 |
| Discount    | Mobile callout waived (repeat customer) |
| VAT (20%)   | £38.71                                  |
| Total       | £232.25                                 |
| Amount paid | £0.00                                   |
| Balance due | £232.25                                 |

## Payment

This is an estimate. Do not pay. To proceed, please contact us to schedule the repair.

**Scope:** Follow-up visit to replace the auxiliary (poly-V) drive belt and belt tensioner assembly on the Mercedes-Benz Sprinter (KR70 PWE). Pulleys will be inspected while accessible. Genuine Mercedes-Benz parts throughout.

**Labour:** 0.9 hrs total per XENTRY manufacturer times (0.7 H replace V-belt + 0.2 H tensioner R&I), charged at the standard rate of £85.00 + VAT per hour.

**Mobile callout:** Standard callout fee (£120.00 + VAT) **waived** as a thank-you for repeat business.

**Parts pricing note:** Genuine MB parts priced at £106.45 inc VAT (tensioner) and £33.99 inc VAT (belt). Line items show ex-VAT values; total VAT shown in the totals box below.

This estimate is valid for 30 days. Final invoice will reflect actual work carried out.

---

[Cancellation & deposit policy](#) · [Terms of service](#) · [Privacy policy](#) · [Disclaimer](#)

Thank you for your business. Questions? Reply to this email or contact us at [contact@tripointdiagnostics.co.uk](mailto:contact@tripointdiagnostics.co.uk)

© 2026 Tripoint Diagnostics Ltd. All rights reserved.