



Estimate

DPF Sensor & Lines Replacement + Service Regeneration

Tripoint Diagnostics Ltd

Company No. 17038307

Registered office: 476 Sidcup Road, London, United Kingdom, SE9 4HA

VAT No.: 515 7327 92 Website: tripointdiagnostics.co.uk

Email: contact@tripointdiagnostics.co.uk | Phone: [020 8058 6095](tel:02080586095)

WhatsApp: [Message us](#) | [Google Business](#)

ESTIMATE NUMBER

EST-2026-0016

STATUS

ESTIMATE

ESTIMATE DATE

21 May 2026

DUE DATE

Valid for 30 days

PAYMENT TERMS

Estimate

BILL TO

Alexandra Security Ltd

SERVICE ADDRESS

Unit 1 Perimeter Works
Whetsted Road, Five Oak Green
Tonbridge, Kent, TN12 6PZ

FAO: Bruce Dickson

Alexandra Security Ltd

Unit 1 Perimeter Works

Whetsted Road

Five Oak Green

Tonbridge, Kent

TN12 6PZ

Vehicle: Mercedes-Benz Sprinter 314 Chassis Long (W906, 2016) (NK17 OFR) **Odometer:** - **Job**

ID: EST-2026-0016 **PO:** -

Technician: Jamie Armoordon

DESCRIPTION	QTY	RATE	AMOUNT
PARTS (GENUINE MERCEDES-BENZ)			
Genuine Mercedes-Benz DPF Differential Pressure Sensor Part No. A000 905 85 03 OE differential pressure sensor for diesel particulate filter (DPF) monitoring.	1	£66.44	£66.44
Genuine Mercedes-Benz Pressure Line Part No. A906 490 10 39 OE DPF differential-pressure sensor hose / line.	1	£10.01	£10.01
Genuine Mercedes-Benz Pressure Line Part No. A906 490 11 39 OE DPF differential-pressure sensor hose / line.	1	£12.65	£12.65
Genuine Mercedes-Benz Exhaust Gas Temperature Sensor Part No. A000 905 39 05 OE exhaust-gas temperature (EGT) sensor for DPF / aftertreatment monitoring.	1	£97.33	£97.33
LABOUR			
DPF Sensor & Lines Replacement + Service Regeneration Remove and replace DPF differential pressure sensor, both pressure lines and the exhaust gas temperature sensor. Clear stored fault codes, reset relevant adaptations and perform XENTRY-guided service (forced) regeneration to verify DPF function. Includes road test and post-repair quick test.	1.3 hrs	£85.00	£110.50

Subtotal	£296.93
Discount	None (no callout fee on repeat work)
VAT (20%)	£59.39
Total	£356.32
Amount paid	£0.00
Balance due	£356.32

Payment

This is an estimate. Do not pay. To proceed, please contact us to schedule the repair.

Scope (follow-up to invoice TPD-2026-0030): Replace DPF differential pressure sensor, both DPF pressure lines and the exhaust-gas temperature (EGT) sensor on the Mercedes-Benz Sprinter 314 (NK17 OFR). Clear stored fault codes, reset relevant adaptations and perform a XENTRY-guided service (forced) regeneration to verify correct DPF operation. Includes road test and post-repair quick test.

Vehicle: Mercedes-Benz Sprinter 314 Chassis Long, registration NK17 OFR, VIN **WDB9061352N709852**, model year 2016.

Parts: Genuine Mercedes-Benz parts throughout.

Labour: 1.3 hrs at the standard hourly rate of £85.00 + VAT. No mobile callout fee applied on repeat work.

This estimate is valid for 30 days. Final invoice will reflect actual work carried out.

[Cancellation & deposit policy](#) · [Terms of service](#) · [Privacy policy](#) · [Disclaimer](#)

Thank you for your business. Questions? Reply to this email or contact us at contact@tripointdiagnostics.co.uk

© 2026 Tripoint Diagnostics Ltd. All rights reserved.