



Invoice

Standard Diagnostic Visit (Zone A)

Tripont Diagnostics Ltd

Company No. 17038307

Registered office: 476 Sidcup Road, London, United Kingdom, SE9 4HA

VAT No.: 515 7327 92 Website: tripointdiagnostics.co.uk

Email: contact@tripointdiagnostics.co.uk | Phone: [020 8058 6095](tel:02080586095)

WhatsApp: [Message us](#) | [Google Business](#)

INVOICE NUMBER

TPD-2026-0031

STATUS

UNPAID

INVOICE DATE

22 May 2026

DUE DATE

Due on receipt

PAYMENT TERMS

Due on receipt

BILL TO

Don's Tyres Ltd

SERVICE ADDRESS

Ben's Tyres
85 to 87 Sevenoaks Road
Orpington, BR6 9JW

Don's Tyres Ltd
5-7 Station Road
Longfield
Kent
DA3 7QD

Vehicle: Mercedes-Benz CLS (W218) (-) **Odometer:** 189,529 km **Job ID:** TPD-2026-0031 **PO:**
-
Technician: Jamie Armoordon

DESCRIPTION	QTY	RATE	AMOUNT
DIAGNOSTIC CALL-OUT			
Standard Diagnostic Visit (Zone A)			
Mercedes-Benz CLS (W218) post-ISM replacement investigation:			
• XENTRY connection established and full multi-module quick test • Fault freeze-frame data captured on all available control units • Drivetrain CAN-bus fault triage (engine ECU, ESP, parking system, backup camera, steering column module) • Verbal findings and recommended next steps provided on-site			
	1	£120.00	£120.00

Subtotal	£120.00
Discount	None
VAT (20%)	£24.00
Total	£144.00
Amount paid	£0.00
Balance due	£144.00

Payment

Pay securely online via the link below, or by bank transfer using the details shown.

Bank transfer:

TriPoint Diagnostics Ltd

Sort code: 04-06-05

Account: 30447065

Reference: TPD-2026-0031

[Pay £144.00 Online →](#)

Vehicle: Mercedes-Benz CLS (W218), VIN **WDD2183012A168227**, mileage 189,529 km.

Works carried out: Attended vehicle at Ben's Tyres, Orpington. XENTRY connection established and initial quick test carried out, with fault freeze-frame data captured on all available control units. Multiple drivetrain communication faults identified, including a **CAN bus OFF** condition logged at the engine ECU, with associated communication faults at the **ESP, parking system, backup camera and steering column module**. Findings indicate a wiring or hardware fault following ISM replacement, not a coding issue.

Next step: Full diagnostic visit scheduled for **Sunday 24 May 2026** to investigate root cause. Any follow-up labour or parts will be quoted and invoiced separately.

This invoice: Covers the standard diagnostic visit only (£120.00 + VAT = £144.00 inc VAT).

[Cancellation & deposit policy](#) · [Terms of service](#) · [Privacy policy](#) · [Disclaimer](#)

Thank you for your business. Questions? Reply to this email or contact us at contact@tripointdiagnostics.co.uk

© 2026 Tripoint Diagnostics Ltd. All rights reserved.