Damage Photographs

CLM-2024-1800 · 2021 Toyota Camry · taken 2024-02-14



1. Overall — front three-quarter



2. Overall — rear three-quarter



3. Close-up — Rear bumper assembly



4. Close-up — trunk lid

AUTOSURE · RECEIVED
2024-02-14

Damage Photographs (continued)

CLM-2024-1800 · 2021 Toyota Camry · taken 2024-02-14



5. Close-up — rear parking sensors



6. Odometer



7. VIN plate

Damage Photographs (continued)

CLM-2024-1800 · 2021 Toyota Camry · taken 2024-02-14



9. Additional angle 9



10. Additional angle 10



11. Additional angle 11



12. Additional angle 12

Damage Photographs (continued)

CLM-2024-1800 · 2021 Toyota Camry · taken 2024-02-14



13. Additional angle 13



14. Additional angle 14



15. Additional angle 15



16. Additional angle 16

Damage Photographs (continued)

CLM-2024-1800 · 2021 Toyota Camry · taken 2024-02-14



17. Additional angle 17



18. Additional angle 18



19. Additional angle 19



20. Additional angle 20

Damage Photographs (continued)

CLM-2024-1800 · 2021 Toyota Camry · taken 2024-02-14



21. Additional angle 21



22. Additional angle 22



23. Additional angle 23



24. Additional angle 24

Damage Photographs (continued)

CLM-2024-1800 · 2021 Toyota Camry · taken 2024-02-14



25. Additional angle 25



26. Additional angle 26



27. Additional angle 27



28. Additional angle 28

Damage Photographs (continued)

CLM-2024-1800 · 2021 Toyota Camry · taken 2024-02-14



29. Additional angle 29



30. Additional angle 30



31. Additional angle 31



32. Additional angle 32