Damage Photographs

CLM-2024-2603 · 2020 Volkswagen Tiguan · taken 2024-01-10



1. Overall — front three-quarter



2. Overall — rear three-quarter



3. Close-up — Ignition bypass damage



4. Close-up — steering column

AUTOSURE · RECEIVED
2024-01-10