Intermittent rattle visit

RECORD / DATE	ASSET / JOB
DOC-007 / 2026-09-24	MC01-P09 / MC-J098
STATUS	SOURCE
Observation remains open	Fictional maintenance collection

Reported symptom

On 16 September an intermittent low rattling sound was reported near the purple-band ventilation unit MC01-P09. AUD-007 records the report. Its reference portrait is IMG-009; a still image does not demonstrate an audible fault.

Contractor attendance

The contractor attended on 24 September and did not reproduce the sound during the visit. No component replacement is recorded. AUD-008 gives the outcome. The record does not identify a cause.

Status

Keep the observation open for a further dated note if the sound returns. A failure to reproduce a symptom does not invalidate the earlier observation and does not establish a repair.

Separate jobs

The dusty filter in MC01-F02 and the blue water booster assembly MC01-P03 are different assets. No evidence in this pack connects the rattle to either of them.