Pump mounting observation

RECORD / DATE	ASSET / JOB
DOC-011 / 2026-09-28	CH02-P13 / CH-J211
STATUS	SOURCE
Assessment requested	Fictional maintenance collection

Visible observation

An outer-edge split was visible on a black rubber foot beneath the red pump CH02-P13. The nearby floor and pump connections appeared dry. Sources IMG-092 and AUD-018 record the observation.

Interpretation

This document does not establish whether the visible split affects performance, safety, noise or vibration. No vibration measurement, cause or repair requirement is claimed.

Follow-up

A contractor assessment was requested on 28 September under CH-J211. There is no completion entry in the demonstration pack. No method for lifting or adjusting equipment is provided.

Related but separate

The intact rubber vibration pad in detail image IMG-096 belongs to another invented reference asset. It is not a repaired view of CH02-P13 and must not be presented as a before/after comparison.