Piezo preamp with EQ

[1] Charge amplifier and Baxandall EQ



File: 1-ChargeAmpAndEQ.kicad_sch

[2] Power supply and opamp biasing

2-Power	

File: 2-Power.kicad_sch

[3] Battery & power indicator

File: 3-BatteryIndicator.kicad_sch


[4] Mounting, hardware and accessories


4-MountingAndAccessories	


File: 4-MountingAndAccessories.kicad_sch


Title, Piero Proema I FO
File: 2024_PiezoPreamp3.kicad_sch
Sheet: /
Arx
changing switches, reducing BOM
v3.0: +ON/OFF sw w/ true bypass, +BI mode sw, + DC jack, external pots, -LED trimpo
v3.1: minor PCB improvements


Title: Fiezo	rically t EW	
Size: A4	Date: 2024-03-12	Rev: 3.1
KiCad E.D.A. 8.0.1		ld: 1/5





















Arx
Sheet: /3-BatteryIndicator/
File: 3-BatteryIndicator.kicad_sch


Title: Battery & Power Indicator
Size: A4 Date: 2024-03-12 Rev: 3.1
KiCad E.D.A. 8.0.1 Id: 3/5




H421

LED light guide







what's missing: - knobs for pots

H417

H419

M2.5, L=6mm

M2.5, L=6mm

BOTTOM SCREWS

H418

H420

Stainless steel, flat thin head <1mm, Phillips, M2.5, L=6mm, pitch 0.45.

M2.5, L=6mm

M2.5, L=6mm

Arx		
	ountingAndAccessories/ tingAndAccessories.kicad_sch	
Title: Mounting, hardware and accessories		
Size: A4	Date: 2024-03-12	Rev: 3.1
KiCad E.D.A.	8.0.1	ld: 1/5