
Different conventions
Declared channel values (degrees)
40
30
20
10
0
−10
−20
−30
−40
Raw action
Observed motor


Convert first: target = (−1) × (−30°)
State − target = −1°
Motor angle (degrees)
40
35
30
25
20
15
10
5
0
Motor target
Observed motor