
Different conventions
Declared channel values (degrees)
40
20
0
−20
−40
Raw action
Observed motor
Convert first: target = (−1) × (−30°)
State − target = −1°
Motor angle (degrees)
40
30
20
10
0
Motor target
Observed motor