

Document Title: AeroCam Pro 2 Service Handbook

Product Series: AeroCam

Product Model: AeroCam Pro 2

Document Type: Service Handbook

Language: en-US

Version: 4.0

Release Date: 2026-06-20

Source URL: <https://example.com/support/aerocam-pro-2/service>

This fictional professional model is intentionally easy to confuse with Mini 2.

Verify the full standard product name before servicing the payload system.

Professional payload diagnostics

Error code AP2-90 indicates a dual-camera thermal alignment failure.

Inspect the payload bay connector and repeat optical axis verification.

Mini-series calibration instructions are not compatible with this model.