

Felt added on the ceiling (rod still in): room error below 3 kHz 2.506 → 2.051 dB (-0.454, better)

2026-09-24/metal-rod → 2026-09-24/felt-ceiling · below 3 kHz, 552 of 946 cells moved >0.05 dB toward flat and 368 away from it · 95 tones · 11 calibrated capsules

