

Corner near the capsule hubs stuffed: room error below 3 kHz 1.403 → 1.445 dB (+0.042, worse)

2026-09-25/material-roll → 2026-09-25/corner-stuffed · below 3 kHz, 410 of 946 cells moved >0.05 dB toward flat and 404 away from it · 95 tones · 11 calibrated capsules

