PHOTO LOG

Photo 1: close view of damage, tail lamp assembly.

Photo 2: close view of damage, trunk lid.

Photo 3: close view of damage, body labor.