HEARTLAND REPAIR GROUP

REPAIR ESTIMATE

Estimate no.: EST-6883

Customer: Robert Ibrahim

Vehicle: 2021 Ford Fusion

Description of repair Amount

Tail lamp assembly: $3,303.00

Trunk lid: $3,420.00

Shop supplies: $1,617.00

Total estimate: $8,340.00