

Remove the sharp edge Dat 4 sides

to reduce the bloomding and shear stress

at shangthen the brucket Darting


as a support / ribs between 1 & ...


Adding Ribs with hillets, between the base bracket (3) and bracket (2) to/strengthen the mel

support brucket @ against bendy stress, authoris

B Relocating the mounting holes B and D away from the from the formation edge of bracket @ than to avoid crack or best stress at the best to continue.

Thickness at the location.





@ Add fillits at ealyse ()

@ smoother the sunface out (1)

to strengthen the bracket (2).

by a fillit.