

VEHICLE SERVICE ENGINEERING

FAILURE ANALYSIS & ROOT CAUSE ANALYSIS REPORT

Report No.	RCA-20260929-82EF8	Date	2026-09-29
Service Engineer	Aklesh	Workshop / Branch	Butwal
Customer / Fleet	Surmati Tharu magar	Job Card	BUTW017383

1. Vehicle Identification

Registration	LUPRA01001KHA0987	VIN / Chassis	MB1PREHDT8975
Model	12 M BS6 BUS	Engine	H-SERIES
Emission	BS6	Odometer	86777
Engine Hours	87	Application	PASSENGER

Operating Condition
LOADED

2. Failure Definition

Failure Reported
ENGINE OVERHEATING

Failure Observed
CLUTCH FAN NOT WORKING

Occurrence
One-time | Severity: Medium | System: Engine

Warning / DTC
NO | GOOD

3. First-Principles System Analysis

System Principle
DUE TO CLUTCH FAN NOT WORKING

4. Diagnostic Investigation

Check	Expected	Actual	Result
Visual inspection			
Electrical supply / ground			
Sensor / actuator signal			
Pressure / flow			
Mechanical condition			
Scan tool / DTC			

Parameter	Unit	Expected	Measured	Assessment

Diagnostic Findings
—

Possible Causes Considered / Eliminated
—

5. 5-Why Root Cause Analysis

Why 1	—
Why 2	—
Why 3	—
Why 4	—
Why 5	—

Failure Mode

—

Confirmed Root Cause

—

Root Cause Category

Manufacturing / Material

RCA Status

Confirmed by evidence

6. Corrective / Preventive Action

Corrective Action

—

Preventive Action

—

Repair Verification / Road Test

—

Parts Replaced / Repaired

—

Labour / Workshop Work

—

7. Warranty Assessment

Warranty Recommendation

Not applicable

Technical Justification

—

10. Service Engineer Declaration

The above findings are based on the inspection, diagnostic measurements, available vehicle data, and verification performed during the investigation. The root cause should be considered confirmed only where supporting evidence has been documented and the repair has been verified under the relevant operating condition.

Prepared By	Reviewed / Approved By
Aklesh Service Engineer	
Signature: _____	Signature: _____
Date: _____	Date: _____