HOME TECH ON-SITE DIAGNOSTIC
Field Dispatch No: DISP-70219
Date: 2024-10-07
Appliance Model: FrostLine Side-by-Side
Serial Number: FL-SBS-30455-D
Technician Findings: Compressor failure with a leak in the sealed refrigerant system.
Parts: Compressor $620.00, Sealed system repair $380.00, Labour $150.00
Estimated Cost: $1150.00