



D1 (1 : 1)



Comments:

1. Check assemblability.
2. Perform Assembly as shown in drawing.
3. Make a trial motions of individual mechanisms and moving parts in order to verify the correctness of installation.
4. Protect against damage and corrosion on time waiting for the main installation.

4	2	Washer A10.5	DIN 125 - A 10,5	0	A2	0	
3	2	Hex Nut M10	ISO 4032 - M10	0	A2	0.01	
2	2	LV.A-60-14-AS-M10 x68	LV.A-60-14-AS -M10x68 Elesa+Ganter	0		0.14	Levelling elements
1	1	Frame - Leg1	CB-900 05.01.00.00	0	1.4301	3.58	
Item	Qty.	Name of part	Drawing number, standard	Rev.	Material	Weight Ipcs. kg	Comments
Investor:							
		Weight 1 set 3,9 kg	Drawing name Conveyor Belt 900mm Main Assembly Frame - Leg1				
Engin.	2016-06-05	papacad	Drawing number CB-900 05.00.00.00		Revision 0		
Draw.	2016-06-05	papacad					
Check.	2016-06-05	papacad					
Ver.	2016-06-05	papacad					
Appr.	2016-06-05	papacad					
papacad 3D & 2D CAD PROJECTS free & purchase			www.papacad.com		Scale 1 : 2	Format A1	Sheet 1 / 1