

64 Carbon - Technical Monitoring Report

29 May 2025

Complete

Score	19 / 25 (76%)	Flagged items	4	Actions	1
-------	---------------	---------------	---	---------	---

Inspection Address

10 Una place
Huddersfield
HD2 2BQ

Inspection on behalf of

64 Carbon Ltd

Company Name /reference Number

LAMTHAMS ENG LTD

Conducted on

29.05.2025

Prepared by

John Harrop

Inspection Stage

C3 - Inspection

What type of measure(s) are being inspected?

B1 - Cavity Wall Insulation

Please see the Technical Monitoring Guidance for more details.

Flagged items & Actions

4 flagged, 1 action

Flagged items

4 flagged, 0 actions

Measure

CWI 6 - Have all vents been safeguarded and have redundant vents been sealed?

Fail

Floors not sleeved and showin insulation




Photo 14



Photo 15

Measure

HSCWI 3 - Are all the air bricks and eaves vents clear of insulation material and sleeves installed where appropriate?V

No

Air bricks not sleeved




Photo 17



Photo 18

Measure

HSCWI 4 - Do any faults specific to the measure installed present an immediate risk to the occupier?

No

Measure

HSCWI 5 - Are there any other safety related issues with the installation?

No

Other actions

1 action

Measure

Overall Score

FAIL

In progress | Assignee: David Gregson, Gillian Hoey, Compliance Team | Priority: Low | Due: 05.06.2025 10:15 BST | Created by: David Gregson

LAMTHANS FAIL 10 Una place HD2 2BQ

Floors not sleeved and full of insulation

Technical Monitoring Questions - Score Monitoring

4 / 4 (100%)

SMQ.1 Does the measure installed match the notified measure type?

Yes

SMQ.2 Does the heating system installed match the notified heating system, or has the appropriate proxy been used where applicable?

Yes

Combi boiler




Photo 1

SMQ.3 Does the floor area match the notified floor area?

N/A

SMQ.4 Does the property match the notified property type?

Yes

Measure

4 flagged, 1 action, 13 / 17 (76.47%)

B1 - Cavity Wall Insulation



TMQ 1 - Have all avoidable thermal bridges/heat loss areas which could have been insulated, been insulated ?

YES

TMQ 2 - Has 100% of the measure been installed where possible?

YES

CWI 1 - Is the insulation material suitable for use with the property's exposure level to wind driven rain?

Yes

CWI 2 - Does the form of the construction of the property suggest that it was suitable for the material that has been installed?

Yes

Stone dressed

CWI 3 - Does the current condition of the property suggest that it was suitable for the material that has been installed?

YES




Photo 2




Photo 3



Photo 4




Photo 5




Photo 6



Photo 7



Photo 8



Photo 9



Photo 10



Photo 11

CWI 4 - Does the drilling pattern conform to the appropriate materials compliance certificate?

YES

CWI 5 - Have all injection holes been filled?

YES



Photo 12




Photo 13

CWI 6 - Have all vents been safeguarded and have redundant vents been sealed?

Fail

Floors not sleeved and showin insulation




Photo 14



Photo 15

CWI 7 - Is there any evidence of the escape of insulation?

NO

CWI 8 - Are there any signs of damp or condensation?

NO

CWI 9 - If the cavity wall contains pre-existing insulation, is the additional insulation to be added compatible with the pre-existing insulation as demonstrated by the product certificate?

N/A

HSCWI 1 - Are combustion vents/flues/chimneys clear of insulation and in compliance with HSE/CIGA guidance?

Pass

HSCWI 2 - Have combustion air core vents been fitted where required?

N/A

N/a




Photo 16

HSCWI 3 - Are all the air bricks and eaves vents clear of insulation material and sleeves installed where appropriate?V

No

Air bricks not sleeved




Photo 17



Photo 18

HSCWI 4 - Do any faults specific to the measure installed present an immediate risk to the occupier?

No

HSCWI 5 - Are there any other safety related issues with the installation?

No

Overall Score

FAIL

In progress | Assignee: David Gregson, Gillian Hoey, Compliance Team | Priority: Low | Due:

05.06.2025 10:15 BST | Created by: David Gregson

LAMTHANS FAIL 10 Una place HD2 2BQ

Floors not sleeved and full of insulation

Comments

B4 - External Wall Insulation ☐

B5 - Flat Roof Insulation ☐

B6 - Floor Insulation ☐

B8 - Internal Wall Insulation ☐

B9 - Loft Insulation ☐

B12 - Room in Roof Insulation ☐

C1 - Gas Boiler (Broken Boiler) ☐

C1 - Gas Boiler (FTCH) ☐

C5 - Heating Controls ☐

D1 - Electric Storage Heaters (NESH) ☐

D1 - Electric Storage Heater (ESHR) ☐

MCS - Air Source Heat Pumps ☐

MCS - Solar PV ☐

Fails

Fails

Vents not sleeved

Outcome of TM

Overall Conclusion

Fail




Photo 19



Photo 20




Photo 21




Photo 22




Photo 23



Photo 24



Photo 25



Photo 26




Photo 27



Photo 28



Photo 29




Photo 30




Photo 31



Photo 32



Photo 33



Photo 34



Photo 35



Photo 36

Technical Monitoring Agents Signature

29.05.2025 10:17 BST

Date

29.05.2025

Media summary



Photo 1



Photo 2




Photo 3



Photo 4



Photo 5



Photo 6



Photo 7



Photo 8



Photo 9



Photo 10



Photo 11



Photo 12



Photo 13



Photo 14



Photo 15




Photo 16



Photo 17



Photo 18



Photo 19



Photo 20



Photo 21



Photo 22



Photo 23



Photo 24



Photo 25



Photo 26



Photo 27



Photo 28



Photo 29




Photo 30



Photo 31



Photo 32



Photo 33



Photo 34



Photo 35



Photo 36