```
{
  "attributes": null,
  "chassis": "CSR1000V",
  "chassis_sn": "9Y23RGWSFML",
  "commands": null,
  "config_register": "0x2102",
  "connections": null,
  "context_manager": {},
  "dir": "bootflash:/",
  "image": "bootflash:packages.conf",
  "issu_rollback_timer_reason": "no ISSU operation is in progress",
  "issu_rollback_timer_state": "inactive",
  "main_mem": "1105351",
  "os": "iosxe",
  "redundancy_communication": false,
  "redundancy_mode": "Non-redundant",
  "rp_uptime": 7980,
  "rtr_type": "CSR1000V",
  "slot": {
    "oc": {
       "F0": {
         "name": "CSR1000V",
         "sn": "",
         "state": "ok, active"
       }
```

```
},
  "rp": {
    "R0": {
       "config_register": "0x2102",
       "issu": {
         "in_progress": false
       },
       "name": "CSR1000V",
       "redundancy_state": "ACTIVE",
       "rp_uptime": "2 hours, 13 minutes",
       "sn": "JAB1303001C",
       "state": "ok, active",
       "system_image": "Cisco IOS Software [Amsterdam], Virtual XE Software (X86_64_LINUX_IOSD-UNIVERSALK9-M), Version 17.3.2, RELEASE SOFTWARE (fc3)"
  }
},
"switchover_reason": "none",
"version": "17.3.2"
```