

Detailed Diagnostic Report

PROPERTY DETAILS

- * Property Age: Not Available
- * Number of Floors: 11
- * Property Type: Flat
- * Previous Structural Audit: No
- * Previous Repair Work: No

EXECUTIVE SUMMARY

The inspection report highlights various defects and issues with the property, including dampness, leakage, and crack-related problems. The report flags one item, and no actions have been taken. The inspection was conducted on September 27, 2022, by Krushna and Mahesh.

OBSERVED DEFECTS

Dampness Related Issues

- * Dampness observed at the skirting level of the hall, bedroom, master bedroom, and kitchen.
- * Mild dampness observed at the ceiling of the common bathroom.

Leakage Related Issues

- * Leakage observed at the parking ceiling below the flat.
- * Leakage due to concealed plumbing and damage in the Nahani trap/brickbat coba under tile flooring.

Crack Related Issues

- * Cracks observed on the external wall of the building near the master bedroom.
- * Separation cracks observed at the beam-column junction (condition not available).

Tile Joint Issues

- * Gaps observed between tile joints in the common bathroom, master bedroom bathroom, and other areas.
- * Loose plumbing joints and rust around joints and edges.

Surface Deterioration Issues

- * Efflorescence observed on the wall surface of the master bedroom.
- * Algae, fungus, and moss observed on the external wall.

THERMAL ANALYSIS

The thermal findings show a range of hotspots (25.1-28.8) and coldspots (20.1-23.4). These findings may indicate areas of heat loss or gain, which could be related to the observed defects, such as dampness and leakage. However, without more specific information, it is difficult to determine the exact relationship between the thermal findings and the inspection findings.

ROOT CAUSE ANALYSIS

For every issue:

- Cause: Concealed plumbing, damage in Nahani trap/brickbat coba under tile flooring, and poor maintenance.
- Evidence: Dampness, leakage, cracks, and gaps between tile joints.
- Impact: Water damage, structural deterioration, and potential health risks.

STRUCTURAL RISK ASSESSMENT

The structural risk assessment is classified as Moderate due to the observed cracks, dampness, and leakage issues. However, without more information on the severity and extent of these issues, it is difficult to determine a more precise classification.

RECOMMENDED REPAIR METHODOLOGY

- * Repair Method: Waterproofing, plastering, and replacement of damaged tiles and plumbing fixtures.
- * Material Required: Waterproofing membrane, plaster, tiles, and plumbing fixtures.
- * Priority: High priority for waterproofing and repair of damaged areas to prevent further deterioration.

CONSEQUENCES OF DELAY

Delay in repair work may lead to further deterioration of the structure, increased risk of water damage, and potential health risks. It may also lead to more extensive and costly repairs in the future.

CONCLUSION

The inspection report highlights various defects and issues with the property, including dampness, leakage, and crack-related problems. It is recommended that the necessary repairs be carried out as soon as possible to prevent further deterioration and potential risks. A more detailed investigation and analysis may be required to determine the exact cause and extent of the issues.