

Detailed Diagnostic Report (DDR)

1. PROPERTY ISSUE SUMMARY

- * Dampness at the skirting level in Hall, Bedroom, Master Bedroom, and Kitchen
- * Gaps between tile joints in Common Bathroom and Master Bedroom Bathroom
- * Cracks on the External wall near Master Bedroom
- * Leakage at the Parking ceiling below Flat No. 103
- * Mild dampness at the ceiling of Common Bathroom
- * Plumbing issues and gaps between tile joints in Common Bathroom

2. AREA-WISE OBSERVATIONS

Hall

The Hall area has shown signs of dampness at the skirting level. The thermal camera readings have not specified the exact temperature for this area, but it can be inferred that there is a temperature difference that may be contributing to the dampness.

Bedroom

The Bedroom area also exhibits dampness at the skirting level. Similar to the Hall, the thermal camera readings do not provide a specific temperature for this area, but the presence of dampness suggests a potential temperature or moisture issue.

Master Bedroom

In the Master Bedroom, dampness and efflorescence are observed on the wall surface. The thermal camera readings for this area range from 25.2°C to 27.3°C, indicating a temperature difference that could be contributing to the dampness and efflorescence.

Kitchen

The Kitchen area shows dampness at the skirting level, similar to the other areas. The thermal camera readings for this area are not specified, but the presence of dampness suggests a potential temperature or moisture issue.

Common Bathroom


The Common Bathroom has gaps between tile joints and plumbing issues. The thermal camera readings for this area range from 20.2°C to 22.3°C, indicating a cooler temperature that could be contributing to the moisture issues.

External Wall

The External wall near the Master Bedroom has cracks. The thermal camera readings for this area are not specified, but the presence of cracks suggests a potential structural issue.

Parking Area

The Parking area below Flat No. 103 has leakage at the ceiling. The thermal camera readings for this area are not specified, but the presence of leakage suggests a potential water ingress issue.



3. PROBABLE ROOT CAUSE

The probable root cause of the issues is water ingress and moisture accumulation due to various factors such as concealed plumbing leaks, damage to Nahani traps, and gaps between tile joints. The temperature differences observed in the thermal camera readings may also be contributing to the moisture issues.

4. SEVERITY ASSESSMENT

The severity of the problems can be rated as Moderate to Severe. The presence of dampness, efflorescence, and cracks suggests a significant moisture issue that needs to be addressed. The plumbing issues and gaps between tile joints also require attention to prevent further water ingress.

5. RECOMMENDED ACTIONS

To fix the issues, the following steps can be taken:

1. Repair the concealed plumbing leaks and damaged Nahani traps.
2. Seal the gaps between tile joints in the bathrooms and kitchens.
3. Fix the cracks on the External wall near the Master Bedroom.

4. Address the leakage at the Parking ceiling below Flat No. 103.
5. Check and repair any other potential sources of water ingress.

6. ADDITIONAL NOTES

It is recommended to conduct a thorough inspection of the property to identify any other potential issues. The dry-out timeline before cosmetic painting begins should be at least 2-3 weeks to ensure that the areas are completely dry and free of moisture.

7. MISSING OR UNCLEAR INFORMATION

The following information is missing or unclear:

- * Specific thermal camera readings for the Hall, Bedroom, and Kitchen areas
- * Details about the type of paint and manufacturer used on the External wall
- * Condition of the rust marks observed in RCC Beam and Column
- * Condition of the corrosion/spalling of concrete/exposed reinforcement observed in column/beams/roof slab ceiling
- * Expansion joints condition, if any
- * Condition of the openings around the pipes in the external wall
- * Condition of any vegetation growth, dish antennas fixed on the parapet wall
- * Condition of the bird droppings on the external wall and Chajja
- * Condition of the corrosion on metal rods and MS window grills
- * Substrate condition of Plaster
- * Condition of the patchwork plaster required, if any
- * Condition of the entire replaster required, if any
- * Condition of the separation cracks observed at beam-column junction
- * Condition of the leakage observed from the overhead water tank
- * Loose plaster/hollow sound on external surfaces, if observed