

Detailed Diagnostic Report (DDR)

1. PROPERTY ISSUE SUMMARY

- Dampness observed at the skirting level in multiple areas, including the hall, bedroom, kitchen, and master bedroom
- Leakage issues noted in the parking area, common bathroom, and master bedroom bathroom

2. AREA-WISE OBSERVATIONS

Hall

Visible symptoms of dampness were observed at the skirting level, with thermal camera readings indicating a hotspot of 26.5 degrees Celsius and a coldspot of 21.5 degrees Celsius. There were no notable images available for this area.

Bedroom

Dampness was observed at the skirting level, and thermal camera readings showed a hotspot of 27 degrees Celsius and a coldspot of 22 degrees Celsius. No images were available for this area.

Kitchen

Dampness was noted at the skirting level, with thermal camera readings indicating a hotspot of 25.7 degrees Celsius and a coldspot of 20.7 degrees Celsius. No images were available for this area.

Master Bedroom

Efflorescence was observed on the wall surface, and dampness was noted at the skirting level. Thermal camera readings showed a hotspot of 27.3 degrees Celsius and a coldspot of 22.3 degrees Celsius. No images were available for this area.

Common Bathroom

Tile hollowness and plumbing issues were observed, with thermal camera readings indicating a hotspot of 26.9 degrees Celsius and a coldspot of 21.9 degrees Celsius. No images were available for this area.

Parking Area

Leakage was observed at the ceiling, with thermal camera readings showing a hotspot of 25.6 degrees Celsius and a coldspot of 20.6 degrees Celsius. No images were available for this area.

3. PROBABLE ROOT CAUSE

The probable root cause of the issues observed is related to concealed plumbing and leakage from overhead water tanks, which has led to dampness and water damage in various areas of the property. The thermal camera readings suggest that there are significant temperature differences between the hotspots and coldspots, indicating potential moisture intrusion.

4. SEVERITY ASSESSMENT

Overall Rating: Moderate

The issues observed are significant, but they do not appear to be severe enough to cause immediate structural damage. However, if left unaddressed, they could lead to more serious problems in the future.

5. RECOMMENDED ACTIONS

1. Repair any damaged or leaking plumbing fixtures and pipes to prevent further water damage
2. Apply a waterproofing treatment to the affected areas to prevent moisture intrusion

6. ADDITIONAL NOTES

It is recommended that the property owner take immediate action to address the issues observed, and consider hiring a professional to inspect and repair any damaged areas. A dry-out timeline of 2-3 weeks is recommended to ensure that the property is completely dry before any repairs are made.

7. MISSING OR UNCLEAR INFORMATION

- No information was available on the type of paint used on the external walls
- No images were available for most of the areas observed