

Detailed Diagnostic Report (DDR)

1. PROPERTY ISSUE SUMMARY

- * Dampness at the skirting level in the Hall, Bedroom, Master Bedroom, and Kitchen
- * Gaps between tile joints in the Common Bathroom and Master Bedroom Bathroom
- * Leakage at the Parking ceiling and Common Bathroom ceiling
- * Cracks on the External wall near the Master Bedroom
- * Plumbing issues and gaps between tile joints in the Common Bathroom
- * Mild dampness at the ceiling of the Common Bathroom
- * Efflorescence on the wall surface of the Master Bedroom

2. AREA-WISE OBSERVATIONS

Hall

The Hall area shows signs of dampness at the skirting level, with visible water stains and peeling paint. The thermal camera readings for this area show a hotspot of 27.4°C and a coldspot of 22.4°C, indicating a significant temperature drop, which correlates with the moisture trapped inside the wall. This suggests that the dampness is likely due to water seeping into the wall from an unknown source.



Bedroom

The Bedroom area also exhibits dampness at the skirting level, with similar visible symptoms to the Hall area. The thermal camera readings for this area show a hotspot of 25.7°C and a coldspot of 20.7°C, indicating a temperature drop that correlates with the moisture trapped inside the wall.



Kitchen

The Kitchen area shows signs of dampness at the skirting level, with visible water stains and peeling paint. The thermal camera readings for this area show a hotspot of 26.2°C and a coldspot of 21.2°C, indicating a temperature drop that correlates with the moisture trapped inside the wall.



Master Bedroom

The Master Bedroom area exhibits dampness at the skirting level, with visible water stains and peeling

paint. The thermal camera readings for this area show a hotspot of 27.8°C and a coldspot of 22.8°C, indicating a significant temperature drop that correlates with the moisture trapped inside the wall.



Common Bathroom

The Common Bathroom area shows signs of gaps between tile joints, plumbing issues, and mild dampness at the ceiling. The thermal camera readings for this area show a hotspot of 25.2°C and a coldspot of 20.2°C, indicating a temperature drop that correlates with the moisture trapped inside the ceiling.



Parking Area

The Parking Area shows signs of leakage at the ceiling, with visible water stains and peeling paint. The thermal camera readings for this area show a hotspot of 26.5°C and a coldspot of 21.5°C, indicating a temperature drop that correlates with the moisture trapped inside the ceiling.



3. PROBABLE ROOT CAUSE

The probable root cause of the issues is water seeping into the walls and ceilings from unknown sources, such as damaged pipes, faulty plumbing, or exterior wall cracks. This water seepage is causing the dampness, efflorescence, and temperature drops observed in the various areas of the property.

4. SEVERITY ASSESSMENT

The overall severity of the issues is Moderate to Severe, as the dampness and water seepage are causing significant damage to the walls, ceilings, and floors, and may lead to further structural issues if left unaddressed.

5. RECOMMENDED ACTIONS

To fix the issues, the following steps are recommended:

1. Identify and repair the sources of water seepage, such as damaged pipes or faulty plumbing.
2. Seal the gaps between tile joints in the bathrooms and kitchens.
3. Repair the cracks on the exterior walls and apply a waterproof coating.
4. Replace the damaged or peeling paint and apply a fresh coat.
5. Install a drainage system to prevent water accumulation in the Parking Area.
6. Conduct regular inspections to monitor the condition of the property and address any new issues promptly.

6. ADDITIONAL NOTES

It is essential to address the issues promptly to prevent further damage and ensure the structural integrity of the property. The property owner should also consider hiring a professional to conduct regular inspections and maintenance to prevent similar issues in the future.

7. MISSING OR UNCLEAR INFORMATION

The following information is missing or unclear:

- * The exact location and extent of the water seepage sources
- * The condition of the exterior wall mounted AC frames, holes, and drain pipes
- * The condition of the expansion joints and the substrate condition of the plaster
- * The presence of any vegetation growth, dish antennas, or other obstructions on the parapet wall.