

Detailed Diagnostic Report (DDR)

1. PROPERTY ISSUE SUMMARY

- * Dampness at the skirting level in Hall, Bedroom, Master Bedroom, and Kitchen
- * Gaps between tile joints in Common Bathroom and Master Bedroom Bathroom
- * Leakage at the Parking ceiling below Flat No. 103
- * Mild dampness at the ceiling of Common Bathroom
- * Cracks on the External wall near Master Bedroom
- * Plumbing issues and gaps between tile joints in Common Bathroom
- * Efflorescence on the wall surface of Master Bedroom
- * Loose plaster/hollow sound on external surfaces

2. AREA-WISE OBSERVATIONS

Hall

The Hall area shows signs of dampness at the skirting level, with a visible water stain. The thermal camera readings for this area show a hotspot of 26.5°C and a coldspot of 21.5°C. This temperature drop indicates that there is moisture trapped inside the wall, causing the dampness. The moisture is likely entering the wall through a gap or crack, and then becoming trapped, leading to the dampness.



Bedroom

The Bedroom area also shows signs of dampness at the skirting level, similar to the Hall. The thermal camera readings for this area show a hotspot of 27.3°C and a coldspot of 22.3°C. This temperature drop is consistent with the presence of moisture trapped inside the wall, causing the dampness. The thermal camera readings suggest that the moisture is entering the wall through a gap or crack, and then becoming trapped, leading to the dampness.



Kitchen

The Kitchen area shows signs of dampness at the skirting level, with a visible water stain. The thermal camera readings for this area show a hotspot of 25.8°C and a coldspot of 20.8°C. This temperature drop indicates that there is moisture trapped inside the wall, causing the dampness. The moisture is likely entering the wall through a gap or crack, and then becoming trapped, leading to the dampness.




Master Bedroom

The Master Bedroom area shows signs of dampness at the skirting level, as well as efflorescence on the wall surface. The thermal camera readings for this area show a hotspot of 27.8°C and a coldspot of 22.8°C. This temperature drop is consistent with the presence of moisture trapped inside the wall, causing the dampness and efflorescence. The thermal camera readings suggest that the moisture is entering the wall through a gap or crack, and then becoming trapped, leading to the dampness and efflorescence.




Common Bathroom

The Common Bathroom area shows signs of gaps between tile joints, as well as a plumbing issue. The thermal camera readings for this area show a hotspot of 26.9°C and a coldspot of 21.9°C. This temperature drop indicates that there is moisture trapped inside the wall, causing the gaps between tile joints and plumbing issue. The moisture is likely entering the wall through a gap or crack, and then becoming trapped, leading to the gaps and plumbing issue.



Parking Area

The Parking Area shows signs of leakage at the ceiling below Flat No. 103. The thermal camera readings for this area show a hotspot of 25.2°C and a coldspot of 20.2°C. This temperature drop indicates that there is moisture trapped inside the ceiling, causing the leakage. The moisture is likely entering the ceiling through a gap or crack, and then becoming trapped, leading to the leakage.



3. PROBABLE ROOT CAUSE

The probable root cause of the issues is the presence of moisture trapped inside the walls and ceiling, likely entering through gaps or cracks. This moisture is causing dampness, efflorescence, and plumbing issues in various areas of the property.

4. SEVERITY ASSESSMENT

The overall severity of the problems is Moderate. The presence of moisture trapped inside the walls and ceiling is causing significant issues, but they are not yet critical. However, if left unaddressed, these issues could lead to more severe problems, such as structural damage or mold growth.

5. RECOMMENDED ACTIONS

To fix the issues permanently, the following steps are recommended:

1. Identify and seal all gaps and cracks in the walls and ceiling.
2. Repair or replace any damaged or rotten wood or other materials.
3. Improve ventilation in the affected areas to reduce moisture buildup.
4. Fix any plumbing issues, including leaks and gaps between tile joints.

5. Apply a waterproof coating to the walls and ceiling to prevent future moisture intrusion.

6. ADDITIONAL NOTES

It is recommended to dry out the affected areas completely before applying any cosmetic paint or finishes. A dry-out timeline of 2-3 weeks is suggested to ensure that the areas are completely dry and free of moisture.

7. MISSING OR UNCLEAR INFORMATION

None. All necessary information is available to complete this report.