

Industrial Maintenance Inspection Report

SOVEREIGN ON-PREMISE INDUSTRIAL REPORT | Generated: 2026-09-26 11:27:57

Executive Summary

Executive analysis for: Create a professional maintenance inspection report PDF from this document..
Risk assessment completed. RPN calculated: Bearing Spalling=96, Seal Leak=180. Severity High.

Equipment Telemetry & Observations

Telemetry indicates primary components are within allowable operational boundaries, with scheduled maintenance required for wear items.

Component	Baseline	Observed	Status
Turbine T-800	0.8 mm/s	1.2 mm/s	Nominal
Coolant Line	45 PSI	48 PSI	Nominal

Inspection Findings & Risks

Risk assessment highlights slight cavitation in impeller casing. Failure risk is moderate with severity rating 6.

Actionable Recommendations

- Verify suction line alignment.
- Clean and replace hydraulic filter elements.
- Re-inspect vibration thresholds after 72 hours.