

# Industrial Maintenance Inspection Report

SOVEREIGN ON-PREMISE INDUSTRIAL REPORT | Generated: 2026-09-26 11:27:57

## Executive Summary

This executive summary outlines the critical preventive maintenance conducted on the plant chillers.

## Equipment Details

Inspection telemetry on Chiller CH-01 and associated primary coolant pump P-102.

| Unit  | Vibration | Discharge PSI | Bearing Temp |
|-------|-----------|---------------|--------------|
| CH-01 | 2.1 mm/s  | 145 PSI       | 68°C         |
| P-102 | 1.8 mm/s  | 120 PSI       | 62°C         |

## Inspection Findings & Risks

Risk assessment highlights slight cavitation in impeller casing. Failure risk is moderate with severity rating 6.

## Actionable Recommendations

1. Bleed suction line. 2. Verify inlet strainer. 3. Recheck vibration in 72 hours.