

Repair Estimate

Cascade Auto Body · 8742 SE Powell Blvd, Portland, OR 97266 · (503) 555-0291 · License #OR-ARB-2019-5541

ESTIMATE NO. EST-2026-0416

CUSTOMER & VEHICLE INFORMATION	
CUSTOMER NAME Rachel Nguyen	VEHICLE 2021 Honda CR-V EX — Lunar Silver Metallic
VIN 2HKRW2H53MH604817	ESTIMATE DATE 2026-04-16
POLICY REFERENCE AU-2025-CP-04821	DAMAGE TYPE Collision — Rear bumper impact while parked

AFFECTED AREA
Rear bumper cover, driver-side tail light assembly. No structural or mechanical damage observed; vehicle remains drivable.

ITEMIZED REPAIRS		
#	Description	Cost
1	Remove, repair, and refinish rear bumper cover (dent removal, fill, prime, paint match)	\$680.00
2	Replace driver-side tail light assembly (OEM part #33550-TLA-A01)	\$420.00
3	Blend and clear-coat adjacent panels for seamless color match	\$350.00
4	Paint materials, supplies, and hazardous waste disposal	\$220.00
5	Final quality inspection and detail wash	\$180.00

COST SUMMARY		
Parts	\$640.00	TOTAL ESTIMATE \$1,850.00
Labor (8 hours @ \$95.00/hr)	\$760.00	
Materials & Supplies	\$450.00	

ESTIMATED LABOR & TERMS	
TOTAL LABOR HOURS 8	ESTIMATED DURATION 2–3 business days
PARTS SOURCE OEM unless otherwise approved	WARRANTY Lifetime on paint · 1-year on labor

Terms & Conditions: Estimate valid for 30 days from date of issue. Final costs may vary if hidden damage is discovered during disassembly. Payment due upon completion unless arranged with insurer.