✓ Congratulations! You passed!

TO PASS 80% or higher

Keep Learning

grade 100%

Week 3 quiz

LATEST SUBMISSION GRADE 100%		
1.	What color does a sketch entity change to when fully defined by dimensions and constraints? Black. Green. Blue. Red.	1/1 point
	✓ Correct The answer can be found in Fully define a complex sketch.	
2.	Which constraint allows two circles of different diameter to share the same center point? Equal. Concentric. Colinear. Parallel.	1/1 point
	✓ Correct The answer can be found in Fully define a complex sketch.	
3.	When adding draft to an extrude during feature creation what is the name of the feature parameter? Pull. Draft. It must be done after the feature. Taper Angle.	1/1 point
	Correct The answer can be found in Create and shell a drafted part.	
4.	What is a joint limit? A numerical stop in a specific joints travel. The speed at which a joint can rotate or translate. The degrees of freedom or DoF of a joint. The number of joints that can be applied to a model.	1/1 point
	Correct The answer can be found in Edit a joint limit.	
5.	A detailed drawing parts list is a list of components in a design. True False	1/1 point
	✓ Correct The answer can be found in Add a parts table.	