




South Ring Road Area
Chambers within this section:

LV12; LV158; LV67; LV11; LV123; LV113; LV112; LV09; LV111; LV110; LV109; LV108; LV08; LV07;
LV06; LV154; LV38; LV244; LV133; LV134; LV79; LV235; LV78; LV98; LV138; LV37; LV136; LV39;
LV80; LV242; LV139; LV40.

ELV114; ELV48; ELV101; ELV123; ELV104; ELV38; ELV37; ELV36; ELV106; ELV115; ELV107;
ELV43; ELV44; ELV127; ELV98; ELV102; ELV124; ELV129; ELV139; ELV100; ELV99.

MV1; MV2; MV7; MV8.

CV0205; CV0210; CV0215; CV0220; CV0225; CV0310; ZCV0300; FTB0216; FTB0217.

FW25; FW03; FW26; FW48; Separator 2; FW49; FW04.

SW30; SW32; Oil Interceptor 2; SW107; SW33; SW57; SW56; SW93; SW108; SW94; SW58;
SW172; SW31; SW105; SW165; SW173; SWST1; SW97; SW181; SW171; SW59; SW180; SWCT1.

IW4; IW21; IW22; IW2; IW1.

PERUN

DCH

FSA

LOAD BANK
GARAGE

PUMP ROOM

HUB AREA TO REMAIN
AS PER EXISTING SOFT
LANDSCAPED AREA.