Field report

The survey covered forty sites across three regions.
Most sites reported steady flow throughout the quarter.

Two sites reported intermittent faults:

- the northern pumping station
- the river crossing sensor

Recommendations

Replace the sensor at the river crossing before the next season.

End of report.