EXAMPLE DATA - generated in demo/mock mode. Areas of interest, findings and work orders are illustrative and NOT field-verified results.

Site Inspection Report

EXAMPLE Operator - Lease inspection | Prepared 2026-10-16 | Site 55.9492 N, 120.4514 W | LSD: _____

1. Summary

Item	Value
Drone images reviewed	5
Overall severity	**Critical**
Ground close-ups requested	2
Work order priority	Medium
Historical wildfire exposure	moderate (score 52.5)

5 aerial images reviewed; worst finding Critical. 2 need a ground close-up. Images cannot detect gas: confirm on site with calibrated detection.

2. Drone findings (ranked worst first)

#	Photo	Severity	Finding and actions
1		**Critical**	**well_pad_gas_leak_aliso.jpg**: Well pad with visible disturbance and dark ground patches consistent with an active incident response. - Do not approach without the site's emergency/H2S procedures and gas monitoring - Notify the operator's control room or emergency line
2		**Medium**	**pipeline_row.jpg**: Pipeline right-of-way in good overall condition; check one crossing area for erosion/encroachment. - Log the crossing location for follow-up
3		**Low**	**well_pad_construction.jpg**: Active well pad construction: lease footprint change explains the satellite flag. - Confirm with the operator that the activity is planned
4		**Low**	**oil_well_site_yawthorpe.jpg**: Operating well pad with tanks and facilities; containment looks intact from the air, minor housekeeping. - None urgent

#	Photo	Severity	Finding and actions
5		Low	**sagd_well_pad.jpg**: Operating well pad with tanks and facilities; containment looks intact from the air, minor housekeeping. - None urgent

3. Ground inspection



wellhead: Producing gas wellhead with plunger lift; minor staining at a lower connection needs follow-up.

Observed: Wellhead/christmas tree with plunger-lift catcher on top; Dark discolouration below a lower flanged connection (possible weep); Paint wear and light surface rust on the valve bodies; Gauge present but the dial is not legible at this resolution

4. Work order

Field	Detail
Title	Investigate possible weep at the lower wellhead connection
Priority	Medium
Description	Producing gas wellhead with plunger lift; minor staining at a lower connection needs follow-up.
Immediate actions	1. Approach from upwind wearing a calibrated personal H2S/LEL monitor 2. Check the stained connection with a gas detector and leak-detection solution 3. Report the finding to the lease operator/supervisor
Next steps	1. If a leak is confirmed, schedule repair under isolation and a permit 2. Get a close-up photo of the gauge to record a legible reading 3. Touch up the coating at the next maintenance window
Safety notes	1. Wellheads are under pressure: no work without isolation and a permit 2. Sour gas may be present in this region; an image cannot detect H2S. Follow the site's H2S procedures

5. Lease FireSmart

Historical wildfire exposure around this lease: moderate (score 52.5). Generic lease FireSmart checks; follow the operator's procedures and applicable rules.

- Vegetation clearance: keep grass, brush and deadfall cut back around the wellhead, separators, tanks and the flare stack, to the distance in the operator's procedures and permit conditions.

- Flare and hot work: check the flare area is clear of cured grass and debris; follow the hot-work permit and any fire bans or restrictions in force.


- Pipeline right-of-way: maintain mowed or bladed firebreaks along the ROW and lease edge; note slash piles or encroaching fuel for follow-up.

- Overwintering fires: after a fire season nearby, watch for smoke or hot spots from holdover fires in peat and organic soils in spring; report to the BC Wildfire Service.

- Evacuation and H2S muster: confirm the muster point and a second egress route still work if a fire blocks the main access; wildfire smoke and H2S are both reasons to move upwind.

- Check current BC Wildfire Service fire danger, bans and evacuation orders before field work.

6. Wildfire history around the site



Measure	Value
Historical exposure rating	MODERATE (score 52.5 / 100)
Fires within 10km	7 fires, 101 ha
Fires within 25km	37 fires, 1,650 ha
Fires within 50km	87 fires, 10,296 ha
Cause mix within 25 km	human 73%, lightning 0%, unknown 27% (37 fires)
Nearest fire >= 1,000 ha	Boundary Lake (2023), 6,422 ha, 48.1 km

Computed by SiteSense from BC Wildfire Service historical fire incident locations (2015-2025). Historical 2015-2025 exposure, not a forecast. Check current BC Wildfire Service danger ratings and bans.

7. Notes and sources

Images cannot detect gas or H2S: confirm with calibrated detection. AI-assisted draft; verify on site. Not a substitute for permits, regulatory inspection or the operator's procedures. Fire history: BC Wildfire Service, Open Government Licence - British Columbia. Photos: see samples/CREDITS.md.

Inspected by: _____ Supervisor approval: _____