




Floating clock inputs are noise sensitive.
Add a cap to non-CMOS unused clock inputs.