

PPAP vs APQP RELATIONSHIP MAP

How APQP Phase 4 outputs become PPAP Elements | AIAG Core Tools Connection | Quality Head Agents

APQP PHASE → PPAP ELEMENT MAPPING

APQP Phase	APQP Output	→	PPAP Element	Element Name
Phase 1 Plan & Define	Customer Requirements Product Assumptions	→	EI 1 + 2	Design Records & Engineering Change Docs
Phase 2 Product Design	DFMEA DFMEA Review	→	EI 4	Design FMEA (DFMEA)
Phase 2 Product Design	Design Records Dwg/CAD Data	→	EI 1	Design Records (Drawings + CAD)
Phase 3 Process Design	Process Flow Diagram	→	EI 5	Process Flow Diagram
Phase 3 Process Design	PFMEA	→	EI 6	Process FMEA
Phase 3 Process Design	Control Plan (CP)	→	EI 7	Control Plan
Phase 4 Product & Process Validation	MSA Study Results	→	EI 8	MSA Study Results
Phase 4	Dimensional Results (6-piece study)	→	EI 9	Dimensional Results
Phase 4	Material / Perf Test Reports	→	EI 10	Material & Performance Test Results
Phase 4	Initial Process Capability Study (Cpk)	→	EI 11	Initial Process Capability Study
Phase 4	Production Trial Run (300 pcs min)	→	EI 14 + EI 15	Sample Product + Master Sample
Phase 5 Feedback & Corrective	PSW Sign-off (PPAP Approval)	→	EI 18	Part Submission Warrant (PSW) ← KEY OUTPUT

KEY INSIGHT: PSW IS THE PROOF OF APQP COMPLETION

The Part Submission Warrant (PSW — Element 18) is the FINAL deliverable that confirms all 17 preceding PPAP elements are complete and acceptable. It is signed by the supplier Quality Manager and approved by the customer. PSW approval = authorization to ship production parts.