## milling machine

elaborato:

Andrea De Paoli VR421742 giordano bellini VR414014

## read README.blif first

The implementation of the machine control system had required four states, one undefined for the starting point of the machine and other three for each section. When turned on the machine require three consecutive bit T taken to the fsm, which will respond with the correct gates opening. The datapath analyze gates and according to them will work on the correct registers. on overflof error register will reset

Following a flow chart of each file with relative variables between them:





