HARNESS HUD / TEST DATASHEET

TOP LEFT TOP RIGHT

J1 connector pinout

Illustrative signals. Not an approved drawing.

PIN	SIGNAL	WIRE
1	+12 V	RED
2	GROUND	BLACK
3	CAN H	WHITE
4	CAN L	BLUE

Orientation: mating face

Confirm cavity numbering on the approved connector drawing before actual wiring.

Try: Zoom 3x, then Move with the arrows.

BOTTOM LEFT BOTTOM RIGHT

HARNESS HUD / TEST DATASHEET

TOP LEFT TOP RIGHT

Inspection reference

1. Verify drawing and revision.

2. Check wire IDs and cavities.

3. Inspect crimps and strain relief.

4. Test continuity and isolation.

5. Record results using approved criteria.

Zoom movement check

Use Move mode to reach each page edge.

Enter or Back exits Move mode.