USB Port to RS-485/
422 Converter

NC

GND

RXD +

RXD -

T/R +

T/R -

ELD - 1

20 GND

#1

19 TXD

18 RXD

17 T2

16 T1

ELD - 2

20 GND

19 TXD

18 RXD

17 T2

#2

16 T1

#1. Multiple ELDs to be wired sequentially (daisy-chained)

#2. Jumper to be placed across T1 & T2 for internal resistance for subsequent ELDs

ELD Logging
Wiring diagram

Rev 1.0
15/05/2020