

PHASE 3

BOOTH SHUTDOWN & RUN COMPLETION

Shutdown checklist and run close-out after clarity is confirmed

App Checkpoint
26

Critical Control

Manual/Inferred

Decision

Critical

Handoff

Complete Shutdown Checklist

App checklist fields — all four must be captured:

- ① Recovery inlets closed
- ② Filtration pump-down started
- ③ Nitrogen off
- ④ Dewax inlet closed

27

Mark Run Complete

App

App button: Mark Run Complete.
Records run completion and closes the linked reactor event.

28

Select Post-Extraction Pathway

Handoff

App choices: 100 lb pot pour OR 200 lb minor run.
Selection determines which downstream workflow owns the material.

HANDOFF TO DOWNSTREAM

Downstream operator takes ownership of wet outputs