

Category :	SKU:WSCHRSFAFARHB3DNBRBKBKMLSSR2	Inspected Date : 10/09/2026	
	Verified By : Roshana	Inspected By : Nelima / Pankaj	
Production Qty : 300	Checked Qty : 300	Pass Qty : 292	Rejection Qty : 08

Qc Inspection Check points

Check points (Backrest)	Status	Check points (Headrest & Assembly)	Status
C98 - Clothes amage & Line mark	Ok	Insert missing - butterfly outer	Ok
Inner thread damage	Ok	Metal patti fixing denut Thread damage	Ok
Butterfly inner broken	Ok	Bend - Butterfly inner	Ok
Butterfly inner - denut missing	Ok	Silver mark - Butterfly mb takia mechanism	Ok
Wrinkle - C98 wire mesh	Ok	Short Fill - Butterfly mb takia mechanism	Ok
Insert missing inner	Ok	Ejection pin mark MB Takiya	Ok
Star lock locating area broken while Star loc	Ok	HB takia outer pin damage	Ok
Gap between inner and fly outer	Ok	Dent Mark - Butterfly MB takia	Ok
Butterfly outer mounting hole damage	Ok	MB pu foam - daamge	Ok
Butterfly outer Bend	Ok	HB takia mechanism damage	Ok
Butterfly Outer Damage	Ok	Bolt broken in HB takia mechanism	Ok
Butterfly outer Scratches	Ok	Hb takia inner bend	Ok
Butterfly outer shortfill	Ok	HB takia outer bend	Ok
Butterfly inner Thread damage	Ok	HB pu foam damage	Ok
Clothes damage - knitted air mesh	Ok	Bolt broken in Hector takia outer	Ok
Amul Bush damage	Ok	Handle lock working	Ok
Outer damage - MB Takia outer	Ok	Handle sagging	Ok
Mold mark - MB takia outer	Ok	Mechanism lock working	Ok
Outer scratch - MB takia outer	Ok	Mechanism recline conduction	Ok
MB takia Mechanism part damage	Ok	Seat comfort	Ok
Shrinkage in butterfly outer	Ok	Chair tilted condiction	Ok

Checking images



Defect reason : Scratch mark in outer, stain matk, mesh

Quality : Sumanta	Production Assembly line : Shakti	Packaging line : Shubham
-------------------	-----------------------------------	--------------------------