

Wakefit Innovation Ltd



Quality Inspection Report - Page 1/1

Category : Maven Mid Back Black & Grey Office Chair

SKU : WSCHRMAVENMBNBBKGYBK

Inspected Date : 10/09/2026

Verified By : Roshana

Inspected By : Ezra

Production Qty : 130

Checked Qty : 130

Pass Qty : 130

Rejection Qty : 04

Qc Inspection Check points

Check points (Backrest)	Status	Check points (Headrest & Assembly)	Status
Foam net dark black- damage	Ok	Maven bottom body (Black)(L) - White mark	Ok
Foam net dark black- Fitment issue	Ok	Maven bottom body (Black) (R) - Scratch	Ok
Maven backrest black - Insert missing	Ok	Maven bottom body (Black) (R)- Dent mark	Ok
Maven backrest black - White mark	Ok	Maven bottom body (Black) (R)- Shrinkage	Ok
Maven backrest black - scratch	Ok	Maven bottom body (Black)(R) - Finishing issue	Ok
Maven lumber support black - scratches	Ok	Maven bottom body (Black)(R) - White mark	Ok
Maven lumber support black - whitemark	Ok	Maven Armrest Pad&Bottom Cover (Black) - Scratches	Ok
Maven armrest black upper body (L)- damage	Ok	Maven Armrest Pad&Bottom Cover (Black) - Dent mark	Ok
Maven armrest black upper body (L) - scratch	Ok	Maven Armrest Pad&Bottom Cover (Black) - White mark	Ok
Maven armrest black upper body (L) - White mark	Ok	Maven Armrest Spare Part (Black) - damage	Ok
Maven armrest black upper body (L) - Insert missing	Ok	Bolt thread damage - Maven black handle (L)	Ok
Maven armrest black upper body (L) - Insert thread damage	Ok	Bolt thread damage - Maven black handle (R)	Ok
Maven armrest black upper body (R)- damage	Ok	Handle lock working	Ok
Maven armrest black upper body (R) - scratch	Ok	Handle sagging	Ok
Maven armrest black upper body (R) - White mark	Ok	Cap missing - Black handle	Ok
Maven armrest black upper body (R) - Insert missing	Ok	Cap fitting condition	Ok
Maven armrest black upper body (R) - Insert thread damage	Ok	Mechanism lock working	Ok
Maven bottom body (Black) (L) - Scratch	Ok	Mechanism recline conduction	Ok
Maven bottom body (Black) (L)- Dent mark	Ok	Armrest and mechanism bolt missing	Ok
Maven bottom body (Black) (L)- Shrinkage	Ok	Seat comfort	Ok
Maven bottom body (Black)(L) - Finishing issue	Ok	Chair tilted conduction	Ok

Checking images



Defect reason : backrest bend, Flash mark

Quality : Sumanta

Production Assembly line : Shakthi

Packaging line : Shubham

[illegible]