	Modified Rule	O/ OO	Date 30.05.2018	Detail* New Rule Made
	20		SD-MS-013	New rolls made
reduction machine shop	Produce part and Hand over part			
		1		
tandard Room	1-Etching marking and inspect the 2-Hand over to production machin			
roduction machine shop	1-Production put part in Jig with v 2-Hand over to production heat tr		location for gears and 5t	th loaction for shaft)
roduction HT	Heat treatment process	<u> </u>		
	Gears		Sha	aff
	Broach Gears "HT will Hand over for Lead profile inspection. Honning gears HT will hand over for honing and inspection at STD	to Machine shop	vill hand over main shaft nine shop for straighteni	and counter shaft to
	L Ji			
PRODUCTION HT	HT move the part with Full Lot wi			ad profile graph /Splin
	major dia/OBD etc with lot control	sneet and HT Inspection re	eport.	
	→ Plot BHT & AHT trend on trend		II be done to make sof	
roduction machine shop	and signed by section head on 1-If trend is towards UCL or LC 2-If abnormal distortion is com			34 - 15-41
roduction machine shop CFT REVIEW MEETING) EAD ROLE:-PROD MC SHOP EMBER :-1-PROD HT 2-M.E 3- INPROCESS QA	1-If trend is towards UCL or LC 2-If abnormal distortion is com 1-CFT will analyze trend chart of any abnormality is observed in 1-Trial to be taken as per input 2-Inprocess QA will share trail 3-ME will share the data to PE 1	on fortnightly basis summin distortion following act of CFT MEMBERS. result to CFT Members. for target setting. (MOM to modify target value in	be done.)	ease modified proces