

Fire Alarm Certificate of Inspection

Fire Alarm serviced in accordance with BS 5839 PT1

Client and Job	Details							
Contract 3007				Job Number 8979				
Client				Appointment Date/Time 24/01/18 09:00				
	BIRTLEY HOUSE			Contract Type Standard A				
	BRAMLEY			Panel Type				
	GUILDFORD			Panel Location 1ST FLOOR				
	SURREY			Category				
Camtant	GU5 0LB			Further visit required+when 24-01-2018				
Telephone	ontact TIM WHALLEY			Quotation to be sent to client				
email	•			Percentage of devices tested 50%				
Battery Readings				False Alarms				
Batt = [(lq x ts) + (la x 1.25)] Ah				Total No of automatic devices (x)	218			
				Total false alarms over last 12 months (from customers log book or ARC)	0			
Quiescent Currer	nt (Iq) (A)			Rate of false alarms per 40 devices	0.00			
Alarm Current (la	a) (A)			Requires investigation (if more than 2 per 40 devices 2 or from same device)	NA			
Battery Standby I	Period required (ts) (hrs)			Maintenance Information				
Battery Required	(Batt) (Ah)	0.00		Last maintenance undertaken	24/01/2018			
Size Fitted	(Ah)			Next maintenance due	01/01/2019			
Date Fitted				Existing BAFE CoC on system				
Operational Te	ests							
Test				Test				
Site requested no	ot to test sounders		True	Site requested not to test outputs	☑			
Confirm signals r	received to ARC (fire & fault)		Ø	Audible alarm devices checked (mains & battery)	Ø			
Open/Short circuit - indicator, buzzer & zone ok			V	Visual alarm devices checked (mains & battery)				
Open/Short circuit - all alarm circuits ok			V	Consumables checked and found to be sufficient	Ø			
Open/Short circuit - all other monitored circuits ok			V	Functional test of emergency lighting				
Mains disconnected - indicator & buzzer ok			V	Panel function zones tested	Ø			
Battery disconne	cted - indicator & buzzer ok		V	All other controls tested e.g. access codes, keyswitch etc.				
Readily available cable & fittings inspected			Ø	Any changes of use of building which may affect fire alarm				
Any changes of construction of building which may affect fire ala								
Final Checks								
Check with monit received	toring station that "fire" signals have beer	1		Set systems for normal operation Record test in log book	☑ ☑			
	of compliance issued?			Graphic zone chart available				
BAFE Certificate	· · · · · · · · · · · · · · · · · · ·			System satisfactory	☑			
	Trainibol			Cystom satisfactory				
Notes:								
Comments (The extent of liability of the signatory is limited to the system as described in the engineers comments, if any)								
50% service heat/smoke detection, mcp'pos;s all ground glr areas and basement plant room areas. site requested that sounders not be tested.								
Variations from the recommendations of BS 5839-1 - Clause 45 – for periodic or annual inspection and test:								

Visit our website on www.eflfire.co.uk
Unit 17 Northbrook Business Park, Worthing, West Sussex, BN14 8PQ



Fire Alarm Certificate of Inspection

Fire Alarm serviced in accordance with BS 5839 PT1

Equipment Inspected Description	Qty Expected	Service Code
INPUT / OUTPUT MODULE	7	INS
OTHER	2	INS
PANEL	1	INS
REPEATER PANEL	1	INS
SOUNDER / BELL	50	INS

I/We being the competent person(s) responsible for the servicing of the system(s) described above certify that the work complies with the recommendations of Clause 45 of BS 5839-1 except for the variations identified above, if any, stated in this certificate and in accordance with BAFE Scheme SP203-1

Timesheets Date on Site	Arrival	Departure	Customer Name / Signature	Engineers Name / Signature
24/01/2018	09:31:00	13:00:00	mario fuchs	Phil Smith